Hot Spots on the Field

triangle is not a run-up area. Note the location of the hold bar. This area is commonly mistaken as such. (See Image Below) One area on the airport to be particularly aware of is the approach end hold bar for runway 32 on taxiway delta. The large, paved

